

Issue identified with H72-EK and H84-EK in Specific Applications

We have received reports from the field that the Ilco Electronic Key H72-EK and H84-EK fail to function properly in a very small percentage of 1999 Ford Windstar and 1999, 2000 and 2001 model year Ford Expedition, Taurus and F-150 vehicles. Testing has revealed that the key electronics, when inserted into the keyway, is more than the maximum distance allowed from the ignition antenna. As a result we are recommending that the H72-EK and H84-EK not be used for these models until a redesigned key can be introduced. We regret any inconvenience that this may cause you, and we assure you that we are continuing to explore the quickest possible solution to resolve this issue.

